

安全评价报告信息公开表

安全评价项目名称	娄烦县裕隆矿业有限公司（刁王沟尾矿库）（干堆）安全现状评价		
项目组长	许爱民	技术负责人	公文革
过程控制负责人	张丽君	报告编制人	许爱民、石 慧
报告审核人	赵艳军	报告提交时间	2024 年 11 月
参与评价工作的安全评价师	姓名	资格证书编号	专业技术能力
	许爱民	S011013000110192000407	安全
	李泽源	1800000000300228	采矿
	柴永喆	S011013000110192000517	电气
	石 慧	S011013000110192000358	地质
	牟 勇	0800000000204207	水工
	程 晨	S011013000110193000341	机械
参与评价工作的技术专家	姓名		/
到现场开展安全评价工作情况	姓名	到现场时间	主要任务
	许爱民、李泽源等	2024 年 8 月 10 日	收集现场资料、查看现场
	许爱民、李泽源等	2024 年 9 月 15 日	整改问题复核
安全评价项目简介	娄烦县裕隆矿业有限公司选矿厂位于娄烦县马家庄乡进善村西南 3km 处的刁王沟内南侧的台地上，娄烦县裕隆矿业有限公司尾矿库位于北侧的刁王沟支沟内，为山谷型干堆尾矿库。等别为四等。尾矿库总坝高 45.0m，总库容 36.5 万 m ³ ，使用年限为 5.3 年。		

<p>安全评价 结论</p>	<p>娄烦县裕隆矿业有限公司（刁王沟尾矿库）（干堆）安全设施及安全管理现状符合《尾矿库安全规程》、《尾矿库安全监督管理规定》、《非煤矿山企业安全生产许可证实施办法》及初步设计（安全专篇）等要求，设施完好，管理到位，具备继续生产运行的安全生产条件。</p>
<p>现场勘察 图片</p>	 <p>The top photograph shows two men standing next to a solar panel mounted on a metal pole, which is connected to a white electrical control box. In the background, there are industrial buildings and a hillside. The bottom photograph shows a dirt road leading up a steep, eroded hillside. A blue sign with white text '1555m' is visible in the foreground. A black SUV is parked on the road, and two men are standing nearby.</p>